

#TodoParaTuRefaccionaria



tmk®

Miscelánea Automotriz



073-974402512SM

ESPECIFICACIONES:

Posición: Trasera

Tipo: Disco

BALATA

HYUNDAI
TUCSON 1.6L/2.5L 22-26

 55.5558.6318

 55.9331.4246 / 55.4999.4015

 ALBERTO BRANIFF 119, AVIACIÓN CIVIL, VENUSTIANO CARRANZA, 15740, CDMX